

## Hyundai Santa Fe 2.2CRDi 150HP

1. Box type: VT101201

2. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

