

## Honda CR-V 2.2i-CDTi 140HP

1. Box type: VT101201
2. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

