

BMW F32 428i 245HP

- 1. Box type: VT401200-013.
- 2. Find plugs for intake manifold pressure sensors. Disconnect them and connect box adapters between.



3. If box is equipped with yellow-red wire connect it to positive terminal in an engine compartment.