

## Seat Leon FR 2.0TSI 280HP



1. Box type: VT401200-040.
2. Find two plugs for manifold pressure sensors. Disconnect them and connect box adapters between. It's easy to access to one of them from the bottom of the engine after removing lower engine dust shield.



